

Modifiche alla configurazione dei controller

Data	Modifica
20250403	Wireless LAN > Virtual AP > eduroam-setup > RF > Allowed band:=g
20250403	Cloned System > AP > AP group > default in default-flex-5-6GHz modifying AP system in default-flex-5-6GHz
20250403	Cloned System > AP > AP System > default in default-flex-5-6GHz modifying Flex Dual Band Mode:5GHz-and-6GHz
20250403	System > Profiles > Wireless LAN > Virtual AP > eduroam > RF > Allow 6GHz band:=yes
20250403	System > Profiles > RF Management > 6 GHz radio: Advertise AP Name for 6GHz Radio = yes, Basic rates 6 = no, Transmit rates 6,9 = no, Transmit EIRP=27dbm
20250403	disabled SSID eduroam-r
20250403	Switched System > Profiles > AP > AP Group > <group> > Regulatory Domain profile to mydefault-6GHz for AP groups: EOM, EOMBiblioCCpt, Tigor, default, default-st123, exubitions
20250403	ap-console-password e backup password settata per System > Profiles > AP > AP System: default default-orig LedOff NoAuthApSystem
20250402	Added 6GHz channels 1,5,9,13,17,21,25,29,33,37,41,45,49,53,57,61,65,69,73,77,81,85,89,93 to multiple ap regulatory-domain-profiles: MaxCoverage_rdp_ui, mydefault-6GHz, TriesteNEXToutdoor_rdp_ui
20250402	Enabled MBO on eduroam ssid (SSID profile)

From:

<https://docu.units.it/dokuwiki/> - Area dei Servizi ICT - Documentation



Permanent link:

<https://docu.units.it/dokuwiki/rete:aruba-wireless-changelog>

Last update: **2025/04/07 11:48 (4 giorni fa)**